

Illustrated Parts List - IPL Update



Product Name(s)

61

Description of change

Removal of Plug 503 27 90-04.
Reason: The plug does not fill any function anymore.

Comments


Introduced from

Serial number / Date	Remark
2006-01-01	The part has not been used in production since 2006.

IPL updates

Page Title	Ref. No	New part no	Name	Excl. part no.	Remark
Crankcase	22		PLUG	503 27 90-04	Remain as spare part

1. Crankcase



Remove plug 503 27 90-04 (pos. 22).